

The logo for tsunami, featuring the word "tsunami" in a bold, white, lowercase sans-serif font on a black background. To the right of the text are three stylized, curved lines in shades of blue and white, suggesting waves or a tsunami.

TSUNAMI® 100 PROGRAM ELIMINATES EXCESSIVE ODOR AT MIDWESTERN POTATO PROCESSOR

Problem:

Excessive odor generated during manufacture of skin-on product due to microbial proliferation on potato surface.

Solution:

The system was currently untreated so a kill study determined that feed of the Tsunami 100 product to the sorter flume would yield effective microbial control.

Results:

Aerobic plate counts in the flume were reduced from 30 million to less than 3,000/mL. These results convinced the plant to treat the entire plant flume system with Tsunami 100.