
Protecting Patients with Accuracy



Ecolab[®] Hand Hygiene Program

Compliance Monitoring System



Hand hygiene is the first defense against healthcare-associated infections (HAIs), yet studies show healthcare workers are less than **40%** compliant.¹

We're changing all of that by providing a new electronic solution for measuring hand hygiene compliance.

The **Compliance Monitoring System** helps your hospital accurately monitor hand hygiene to encourage positive change. As handwashing compliance increases, the risk of HAIs decreases and patient outcomes improve.



Reach compliance goals of **90%** or higher with the electronic system that measures up to **100%** of all hand hygiene events.²

The Most Accurate Way to Monitor Compliance

You now have the ability to transform the way your hospital creates, monitors and reports hand hygiene compliance.

The Patient Zone

The bed kit creates a zone around the patient to indicate if the healthcare worker washes their hands or sanitizes before and after patient contact.

Robust Reporting

Data is compiled to track compliance by individual, department, hospital, and system. Equipment status, sanitizer and soap levels, and battery life are also reported.

Immediate Feedback

The badge, worn by all healthcare workers, measures and records every hand hygiene event by individual. Visual and audible feedback is immediate.


Little to No IT Involvement


The system is not tied to the hospital's network. It does not utilize private or public Wi-Fi, and does not require hardwiring.

Immediate Action Monitoring (IAM)

The badge monitors individual hand hygiene events. Green, yellow and red lights deliver immediate feedback based on compliance, driving increased hand hygiene compliance. The badge can also emit an audible beep when a reminder is required. This sends a strong message that patient safety comes first.

- IAM Green = Healthcare worker is compliant
- IAM Yellow = Healthcare worker needs a reminder
- IAM Red = Healthcare worker is not compliant





Robust Dashboard Reporting

The dashboard displays compliance trends in several different ways. You can see how the overall hospital is doing over the past 3 months, or look at results in real-time. You can access all the reports directly on the dashboard, or have them emailed to you directly. All of this with little to no IT involvement.



Battery Report

	No Activity Report
last 10 days: (181)	Ecolab [*] Hand Hygiene Program

Departments:	All	•		
Badges (50	0)			
Badge	Employee	Department	Battery	Last Ping
0A0044C4	Elliott Sue	Case Management	Low	2017-05-08 15:31:15
0A004B93	Perkins Wilma	Dietary	Low	2017-05-08 12:58:16
0A003BBA	Marquez Terry	Emergency Medicine	Low	2017-05-02 23:05:51
0A00423B	Gilbert Lydia	EVS	Low	2017-05-08 16:25:14
0A003ACE	Harvey Stella	EVS	Low	2017-01-19 17:06:26
0A003C1C	Trujillo Brett	ICU	Replace	2017-05-08 13:57:02
0A004D06	Gomez Nicole	ICU	Replace	2017-05-09 17:59:48
0A004BA7	Meyer Cathy	ICU Step-down	Replace	2017-03-17 07:11:19
0A004511	Farmer Frederick	ICU Step-down	Low	2017-05-10 06:00:38
0A004834	Greer Guy	ICU Step-down	Low	2017-05-08 07:00:45

Employee Nicholson Nell Harris Kimberly Wilson Dorothy Schwartz Jeffrey Williams Linda Blake Afred	Badge 0A003ESD 0A00472A 0A004120 0A00451F 0A0041CF	Department 600 Nursing Administration 611 Medical Unit 611 Medical Unit 611 Medical Unit 611 Medical Unit	Position Supy House Admin RN MediSurg CNA RN	Last Activity 2017-08-01 08:47:36 2016-12-23 18:42:37 2017-01-26 07:21:33 2017-07-20 18:28:36
Harris Kimberly Wilson Dorothy Schwartz Jeffrey Williams Linda	0A00472A 0A004120 0A00451F 0A0041CF	611 Medical Unit 611 Medical Unit 611 Medical Unit	RN Med/Surg CNA	2016-12-23 19:42:37 2017-01-26 07:21:33
Wilson Dorothy Schwartz Jeffrey Williams Linda	0A004120 0A00451F 0A0041CF	611 Medical Unit	CNA	2017-01-26 07:21:33
Schwartz Jeffrey Williams Linda	0A00451F 0A0041CF	611 Medical Unit		
Williams Linda	0A0041CF		RN	2017-07-20 18:28:35
		611 Medical Unit		2011 01 20 10 20 00
Blake Alfred			RN Med/Surg PRN	2017-07-28 18:50:00
	0A003D11	611 Medical Unit	RN	2017-08-03 19:24:09
Briggs Mitchell	0A0043E5	611 Medical Unit	Nursing Student	2017-08-05 19:18:48
Stokes Milton	0A0044CB	611 Medical Unit	CNA	2017-05-21 05:48:41
Martinez Lisa	0A003DEA	611 Medical Unit	RN Med/Surg PRN	2017-07-23 19:59:55
Cardenas Cory	0A00470B	611 Medical Unit	RN	2017-07-28 07:40:30
Moore Sandra	0A004B98	611 Medical Unit	Nursing Student PRN	2017-08-05 18:40:42
Johnson Patricia	0A00411B	611 Medical Unit	RN Med/Surg PRN	2017-08-05 05:55:28
Wright Rebecca	0A0044D5	613 Surgical Unit	Charge RN/Clinical Coord MS	2017-06-30 07:38:28
Scott Kathleen	0A0040CC	613 Surgical Unit	RN	2017-07-30 06:40:09
Day Penny	0A004265	613 Surgical Unit	Registered Nurse	2017-08-05 18:41:10
King Virginia	0A00488C	613 Surgical Unit	Student Nurse	2017-06-27 06:39:14
Schmidt Dolores	0A0044CE	621 Medical Telemetry	RN	2017-05-26 19:08:14
Hunter Suzanne	0A004147	621 Medical Telemetry	RN	2017-07-16 14:08:09

The Complete Program





Nexa[™] dispensers support a variety of Ecolab antimicrobial and general-use hand soaps, hand sanitizers and more.

Driving and sustaining better outcomes starts by learning more about the Compliance Monitoring System.

Visit www.ecolab.com/compliancemonitoring or contact your Ecolab representative.

 Centers for Disease Control and Prevention. Guideline for Hand Hygiene in Healthcare Settings: Recommendations of the Healthcare Infection Control Practices Advisory Committee and the HICPAC/SHEA/APIC/IDSA Hand Hygiene Task Force. MMWR 2002;51 (No. RR-16).
Ecolab data on file.

1 Ecolab Place, St. Paul, MN 55102 www.ecolab.com/healthcare 1.866.781.8787 (US) 1.800.352.5326 (Canada)